TEXAS INSTRUMENTS

12500 TI Boulevard, MS 8640, Dallas, Texas 75243

PCN#20181205001.0A
Pin One Dot Symbolization change – Adding Pin One Dot for Select ~~SC70,~~ SOT-23, and SOT-223 Devices
Information Only

Date: March 07, 2019
To: Newark/Farnell PCN

Dear Customer:

Revision A is to remove the SC70 devices from this PCN as they have always had the pin one dot and were inadvertently included in this notice.

This is an information-only announcement of a change to a device that is currently offered by Texas Instruments.

The changes discussed within this PCN are for your information only. Please see the attachment details for the planned implementation date.

This notification period is per TI's standard process. Any negotiated alternative change requirements will be provided via the customer's defined process. Customers with previously negotiated, special requirements will be handled separately. Any inquiries should be directed to your local Field Sales Representative.

For questions regarding this notice, contact your local Field Sales Representative or the PCN Manager (PCN_ww_admin_team@list.ti.com).

Sincerely,

PCN Team
SC Business Services

Products Affected:

The devices listed on this page are a subset of the complete list of affected devices. According to our records, these are the devices that you have purchased within the past twenty-four (24) months. The corresponding customer part number is also listed, if available.

DEVICE	CUSTOMER PART NUMBER
LM4040BIM7-2.5/NOPB	null
LMV841MG/NOPB	null
LM20BIM7/NOPB	null
LM4041CIM7-1.2/NOPB	null
LM4041CIM7-ADJ/NOPB	null
LM94021BIMG/NOPB	null
LM94022BIMG/NOPB	null
LM94022QBIMG/NOPB	null
LMS33460MG/NOPB	null
LMT84DCKT	null
LMT85DCKT	null
LMT85QDCKTQ1	null
LMT86DCKT	null
LMT86QDCKTQ1	null
LMT87DCKR	null
LMT87DCKT	null
LMT87QDCKTQ1	null
LMT88DCKT	null
LMT89DCKT	null
LMV321M7/NOPB	null
LMV331M7/NOPB	null
LMV551MG/NOPB	null
LMV641MG/NOPB	null
LMV641MGE/NOPB	null
LMV651MG/NOPB	null
LMV7219M7/NOPB	null
LMV721M7/NOPB	null
LMV7239M7/NOPB	null
LMV7271MG/NOPB	null
LMV7275MG/NOPB	null
LMV7291MG/NOPB	null
LMV771MG/NOPB	null
LMV821M7/NOPB	null
LMV831MG/NOPB	null
LMV831MGE/NOPB	null
LMV861MG/NOPB	null
LMV931MG/NOPB	null
LP5951MG-1.8/NOPB	null
LP5951MG-2.5/NOPB	null
LP5951MG-3.3/NOPB	null
LPV321M7/NOPB	null
LPV511MG/NOPB	null
LPV521MG/NOPB	null
LPV521MGE/NOPB	null
LPV7215MG/NOPB	null
TLV521DCKT	null
LM20CIM7/NOPB	null
LMV331M7X/NOPB	null
LMV7235M7/NOPB	null

Technical details of this Product Change follow on the next page(s).

PCN Number:	20181205001.0A		PCN Date:	March 7, 2019
Title:	Pin One Dot Symbolization change – Adding Pin One Dot for Select SC70, SOT-23, and SOT-223 Devices			
Customer Contact:	PCN Manager	Dept:	Quality Services	

Change Type:

☐	Assembly Site	☐	Assembly Process	☐	Assembly Materials
☐	Design	☐	Datasheet	☐	Mechanical Specification
☐	Test Site	☒	Packing/Shipping/Labeling	☐	Test Process
☐	Wafer Bump Site	☐	Wafer Bump Material	☐	Wafer Bump Process
☐	Wafer Fab Site	☐	Wafer Fab Materials	☐	Wafer Fab Process
		☐	Part number change		

PCN Details

Description of Change:

Revision A is to remove the SC70 devices from this PCN as they have always had the pin one dot and were inadvertently included in this notice.

This letter is to inform of the addition of a Pin One dot in the devices symbolization of select SC70, SOT-23, and SOT-223 Devices:

-

	Current Symbolization (No Pin One Dot)	New Symbolization (With Pin One Dot)
SC70 Example		
SOT-23 3 Lead example		
SOT-23 5 Lead example		

SOT-223 4 Lead example		

Reason for Change:

Standardization

Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):

None

Changes to product identification resulting from this PCN:

Device symbolization

Product Affected:

For affected devices, see page 2

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com